

Manhole Inspection Summary

Manhole # S19EE_002MH

Printed On: 6/25/2009

Page 1 of 3

Inspection ☒ **Is Incomplete** Rating:

Record Plat: **19EE** Node: **002** Status: **Not Found**

Insp Date: **3/12/09 9:27 AM**

Incomplete Comments

Cannot Access - Buried - Manhole Existing Confirmed by CCTV

Crew: **ADS4**
Inspector: **ADS4**
Firm: **ADS**

Location Address: **1300 N MONROE ST**

Cross Street: **WINCHESTER ST**

Manhole Type: **Junction** Location: **Other - See Comments**

Ground Conditions: **Dry**

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **BASED ON MAP, THIS MANHOLE IS ON A RAILROAD TRACK AREA. REI / DRAYCO IS NOT CAPABLE OF INSPECTION WORK AT THIS LOCATION.**

Cover Shape: Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)

Type: **Sanitary**

Condition:

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

Chimney / Frame Adjustment ☐ Exists Material: ☐ Parged Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel Material: ☐ Parged Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Barrel Material: ☐ Parged

Shape: Diameter: (in.) Length: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Bench ☐ Exists Material: ☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Channel Material: ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps Count: Missing: ☐ Corroded

Surcharge ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

